

Skullgard® Protective Caps and Hats



Heavy-duty caps and hats, for use in heavy industries, steel mills, and elevated temperatures.

- Features heavy-duty construction for use in steel mills and other heavy industries where elevated temperatures are common.
- Meets or exceeds the applicable requirements for a Type I helmet (top impact) as outlined in ANSI Z89.1-2003, Class G (electrical, low voltage).
- Skullgard Cap--choice of Staz-On®, Fas-Trac®, and Swing-Ratchet Suspensions
- Skullgard Hat--choice of Staz-On and Fas-Trac Suspensions



Staz-On® and Fas-Trac® Ratchet Suspension Systems



Skullgard with Swing-Ratchet Suspension



Ordering Information

Skullgard Assemblies

	Skullgard Cap			Skullgard Hat	
	Staz-On	Fas-Trac	Swing-Ratchet	Staz-On	Fas-Trac
Natural tan	454617	475395	816651	454664	475407
White	454618	475396	•	454665	475408
Yellow	454619	475397	•	454666	•
Red	454620	•	•	•	•
Green	454621	•	•	454668	•
Grey	454622	•	•	•	•
Blue	454623	•	•	•	•
Orange	454626	•	•	454673	•

Alternative Skullgard Assemblies

Large Skullgard Cap with Staz-On suspension, natural tan	82018
Standard Skullgard Cap with Staz-On suspension, lamp bracket and cord holder, natural tan	460409
Skullgard Hat with Staz-On suspension, lamp bracket and cord holder, natural tan	460389
Skullgard Cap with Fas-Trac suspension, Welder's Lugs, natural tan	482002

Replacement Suspensions

Size	Staz-On	Fas-Trac	Fixed-Crown®	Swing Fas-Trac	1-Touch
Std (6½–8)	454231	473334	79717 (6½–7⅝)	816654 (6½–7⅝)	10061128
Large (7–8½)	468096	478454	—	—	—

⚠ WARNING

Do not mix suspension and helmet sizes. Make sure the sizes match (example: standard size suspension with standard size helmet). Use only MSA suspensions on an MSA helmet. Failure to comply with the above will reduce the energy-absorbing ability of the protective helmet, which can result in serious injury or death.



Instant Release Attachments for Welding Shields

Kits permit the easy attachment of Welding Shields and SparkGard Faceshields with visors to MSA's helmets.




Ordering Information

Plastic Instant-Release Attachment	Part No.
Instant-Release, less lugs, for slotted caps	10039111
Lugs only, for instant-release non-slotted caps (G)	48733



Plastic Instant-Release for Welding Helmet



Instant-Release Attachment

Ordering Information

Instant-Release and lugs for non-slotted caps, with stop (A, B, C, D, E, F, G)	91385
Lugs only, for instant-release non-slotted caps (G)	48733
Instant-release, less lugs, with stop (A, B, C, D, E, F)	456667
Friction joints, pair (A, D, E, F)	93631

Visors (Additional visors available)

Ordering Information

Visor Type	Color	Size (inches)	Part No.
Polycarbonate visor (formed)	clear	8 x 16 x .040	488131
Polycarbonate visor (formed)	clear	8 x 16 x .060	488132
Polycarbonate visor (elevated temperature)	clear	8 x 15½ x .080	10005878
Nitrometer visor (use special chinguard P/N 10013631 only) (formed)	Shade 5 (green) propionate	6 x 15½ x .060	10005881
Polycarbonate visor (high heat) (formed)	gold-coated (clear)	8 x 15½ x .060	10005879
Polycarbonate visor (high heat) (formed)	gold-coated (med. green)	8 x 15½ x .060	10005880
Wire screen visor, plastic edge, 20 mesh (not for use in elevated temperatures)		6½ x 14	476356

Note: This Bulletin contains only a general description of the products shown. While uses and performance capabilities are described, under no circumstances shall the products be used by untrained or unqualified individuals and not until the product instructions including any warnings or cautions provided have been thoroughly read and understood. Only they contain the complete and detailed information concerning proper use and care of these products.



ID 0601-12-MC / Feb 2007

© MSA 2007 Printed in U.S.A.

Corporate Headquarters
P.O. Box 426, Pittsburgh, PA 15230 USA
Phone 412-967-3000
www.MSAnet.com

U.S. Customer Service Center
Phone 1-800-MSA-2222
Fax 1-800-967-0398

MSA Canada
Phone 1-800-MSA-2222
Fax 905-238-4151

MSA Mexico
Phone 52-55 21 22 5770
Fax 52-55 53 59 4330

MSA International
Phone 412-967-3354
Fax 412-967-3451

Offices and representatives worldwide

For further information:

Foldback Faceshield Frame



The metal foldback Faceshield Frame with visor provides limited eye and face protection for wearers of MSA Industrial Head Protection.

Ordering Information

Special Foldback Faceshield Frame for Skullgard caps only, metal	10079072
Foldback Faceshield Frame, metal, hat model	488159

⚠ WARNING

Do not use metal Foldback Faceshield Frame in electrical applications. Failure to follow this warning can result in serious injury or death.

Custom Terri-Band Sweatband



Custom Terri-Band Sweatband

Fits all MSA helmets. Provides excellent absorption, is easily washable and has no metal parts. Offers great fit and comfort.

Ordering Information

Custom Terri-Band Sweatband (package of 10)	696688
---	--------

⚠ WARNING

Do not use MSA visor for welding, elevated temperature applications, or for protection against other infrared radiation sources unless MSA visor is approved for such application. Do not use for sports, simulated war games, paintball games, or similar activities. A pitted or scratched lens reduces eye protection and vision. Inspect routinely and replace worn or damaged parts immediately. Do not alter or modify this product. Do not use near open flame. Failure to follow these warnings can result in permanent impairment of sight, other serious personal injury, or death.

MSA
The Safety Company™